

Work Order ID 97136

February-14-13 2:37:40 PM

97136

Page 1

Item ID: D3500-1

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Saddle

Start Date: 2/14/13 Start Qty: 12.00

12

Cust Item ID:

Required Date: 3/08/13 Req'd Qty: 12.00

12

Customer:

Reference:

Approvals:

Process Plan:

Date: 13-02-20

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D3500

C

100

0.00

100

HAAS CNC VERTICAL MACHINING #1

HAAS I

Memo

0.00

HAAS CNC vertical machine #1

Program Batch No. 97136 Double check by: FK 1-Machine Step No 1
per Folio FA641 and inspect per attached Dimension Sheets2-Machine Step
No 2 per Folio FA641 and inspect per attached Dimension Sheets3-Machine
Step No 3 per Folio FA641 and inspect p

12 SL 13-3-31

110

QC2- Inspect parts off machine FAI/FAIB

0.00

110

QC

Memo

0.00

Quality Control

SL 13-3-31

120

QC8- Inspect parts - second check

0.00

120

QC

Memo

0.00

Quality Control

FK 13/04/01

12 Ø

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____

QA Closed: _____ Date: _____

Work Order: _____ Part No. _____ NCR No. _____				DISPOSITION Rework <input type="checkbox"/> Scrap <input type="checkbox"/> Use-as-is <input type="checkbox"/> Work Order Update <input type="checkbox"/>		AGAINST DEPARTMENT/PROCESS <div style="display: flex; justify-content: space-between;"> <div> Skid-tube <input type="checkbox"/> Machining <input type="checkbox"/> Thermoforming <input type="checkbox"/> Large Fab <input type="checkbox"/> </div> <div> Crosstube <input type="checkbox"/> Small Fab <input type="checkbox"/> Finishing <input type="checkbox"/> Composite <input type="checkbox"/> </div> <div> Water Jet <input type="checkbox"/> Prod. Eng. Coord. <input type="checkbox"/> Rec/Store/Packaging <input type="checkbox"/> Supplier <input type="checkbox"/> </div> <div> Engineering <input type="checkbox"/> Quality <input type="checkbox"/> Other <input type="checkbox"/> </div> </div>					
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector		
Doc/Data <input type="checkbox"/>											
Equip/Tooling <input type="checkbox"/>											
Operator <input type="checkbox"/>											
Material <input type="checkbox"/>											
Setup <input type="checkbox"/>											
Other <input type="checkbox"/>											
Process <input type="checkbox"/>											
Supplier <input type="checkbox"/>											
Training <input type="checkbox"/>											
Unapproved <input type="checkbox"/>											
FAULT CATEGORY											
Landing Gear <input type="checkbox"/> Bending <input type="checkbox"/> Centre Not Concentric to O/S <input type="checkbox"/> Cracks <input type="checkbox"/> Crushed/Crimped. <input type="checkbox"/> Cuffs <input type="checkbox"/> Heat Treat <input type="checkbox"/> Inspection Strip in Tube <input type="checkbox"/> Ripples in Bend <input type="checkbox"/> Torque Waves in Extrusion <input type="checkbox"/> Turning Sequence <input type="checkbox"/> Wave/Twist in Tube			General <input type="checkbox"/> Bend <input type="checkbox"/> BOM/Route <input type="checkbox"/> Broken/Damaged <input type="checkbox"/> Burrs <input type="checkbox"/> Contamination <input type="checkbox"/> Countersink <input type="checkbox"/> Cut Too Short <input type="checkbox"/> Drill Holes <input type="checkbox"/> Drawing <input type="checkbox"/> Finish <input type="checkbox"/> Folio			<input type="checkbox"/> Grain <input type="checkbox"/> Hardware <input type="checkbox"/> Inspection Incomplete <input type="checkbox"/> Instructions Incomplete/Unclear <input type="checkbox"/> Maintenance <input type="checkbox"/> Mislabeled <input type="checkbox"/> Misread <input type="checkbox"/> Offset <input type="checkbox"/> Out of Calibration <input type="checkbox"/> Out of Sequence <input type="checkbox"/> Outside Dimensions			<input type="checkbox"/> Ovalized <input type="checkbox"/> Over/Under tolerance <input type="checkbox"/> Part Incorrect <input type="checkbox"/> Part Lost/Missing <input type="checkbox"/> Part Moved <input type="checkbox"/> Positioned Wrong <input type="checkbox"/> Power Loss/Surge <input type="checkbox"/> Pressure/Forced <input type="checkbox"/> Temperature/Cure <input type="checkbox"/> Weld <input type="checkbox"/> Wrong Stock Pulled <input type="checkbox"/> Other		

Work Order ID 97136

February-14-13 2:37:40 PM

97136

Page 2

Item ID: D3500-1

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Item Name: Saddle

Stop ***NS2***

Start Date: 2/14/13 Start Qty: 12.00

12

Cust Item ID:

Required Date: 3/08/13 Req'd Qty: 12.00

12

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start ***NR1***

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

130

Chemical Conversion Coat per QSI005 4.1

0.00

130

HandFinish

Memo

0.00

Hand Finishing

12 26/3-4-2

140

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum

0.00

140

Powdercoat

Memo

0.00

Powder Coating

START TIME:

FINISH TIME:

OVEN TEMPERATURE:

8:30
320°F

9:00

QC3- Inspect Part Finish

0.00

150

150

QC

Memo

0.00

Quality Control

12x 1/2 m/z 13/04/03

12x d Ill 12/04/03

m124245

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____

QA Closed: _____ Date: _____

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework <input type="checkbox"/> Scrap <input type="checkbox"/> Use-as-is <input type="checkbox"/> Work Order Update <input type="checkbox"/>	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube <input type="checkbox"/></td> <td>Crosstube <input type="checkbox"/></td> <td>Water Jet <input type="checkbox"/></td> <td>Engineering <input type="checkbox"/></td> </tr> <tr> <td>Machining <input type="checkbox"/></td> <td>Small Fab <input type="checkbox"/></td> <td>Prod. Eng. Coord. <input type="checkbox"/></td> <td>Quality <input type="checkbox"/></td> </tr> <tr> <td>Thermoforming <input type="checkbox"/></td> <td>Finishing <input type="checkbox"/></td> <td>Rec/Store/Packaging <input type="checkbox"/></td> <td>Other <input type="checkbox"/></td> </tr> <tr> <td>Large Fab <input type="checkbox"/></td> <td>Composite <input type="checkbox"/></td> <td>Supplier <input type="checkbox"/></td> <td></td> </tr> </table>	Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>	Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coord. <input type="checkbox"/>	Quality <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>	
Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>															
Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coord. <input type="checkbox"/>	Quality <input type="checkbox"/>															
Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>															
Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>																

Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data									
Equip/Tooling									
Operator									
Material									
Setup									
Other									
Process									
Supplier									
Training									
Unapproved									

FAULT CATEGORY

Landing Gear	General	Other	Other
<input type="checkbox"/> Bending	<input type="checkbox"/> Bend	<input type="checkbox"/> Grain	<input type="checkbox"/> Ovalized
<input type="checkbox"/> Centre Not Concentric to O/S	<input type="checkbox"/> BOM/Route	<input type="checkbox"/> Hardware	<input type="checkbox"/> Over/Under tolerance
<input type="checkbox"/> Cracks	<input type="checkbox"/> Broken/Damaged	<input type="checkbox"/> Inspection Incomplete	<input type="checkbox"/> Part Incorrect
<input type="checkbox"/> Crushed/Crimped	<input type="checkbox"/> Burrs	<input type="checkbox"/> Instructions Incomplete/Unclear	<input type="checkbox"/> Part Lost/Missing
<input type="checkbox"/> Cuffs	<input type="checkbox"/> Contamination	<input type="checkbox"/> Maintenance	<input type="checkbox"/> Part Moved
<input type="checkbox"/> Heat Treat	<input type="checkbox"/> Countersink	<input type="checkbox"/> Mislabeled	<input type="checkbox"/> Positioned Wrong
<input type="checkbox"/> Inspection Strip in Tube	<input type="checkbox"/> Cut Too Short	<input type="checkbox"/> Misread	<input type="checkbox"/> Power Loss/Surge
<input type="checkbox"/> Ripples in Bend	<input type="checkbox"/> Drill Holes	<input type="checkbox"/> Offset	<input type="checkbox"/> Pressure/Forced
<input type="checkbox"/> Torque Waves in Extrusion	<input type="checkbox"/> Drawing	<input type="checkbox"/> Out of Calibration	<input type="checkbox"/> Temperature/Cure
<input type="checkbox"/> Turning Sequence	<input type="checkbox"/> Finish	<input type="checkbox"/> Out of Sequence	<input type="checkbox"/> Weld
<input type="checkbox"/> Wave/Twist in Tube	<input type="checkbox"/> Folio	<input type="checkbox"/> Outside Dimensions	<input type="checkbox"/> Wrong Stock Pulled
			<input type="checkbox"/> Other

Work Order ID 97136

February-14-13 2:37:40 PM

97136

Page 3

Item ID: D3500-1

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Saddle

Start Date: 2/14/13

Start Qty: 12.00

12

Cust Item ID:

Required Date: 3/08/13

Req'd Qty: 12.00

12

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

160

Identify as per dwg & Stock Location:

0.00

160

Packaging

Memo

STP23

0.00

Packaging

43/5/3 (12)

170

QC21- Final Inspection - Work Order Release

0.00

170

QC

Memo

0.00

Quality Control

13/4/4

RB-04-4

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____

QA Closed: _____ Date: _____

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework <input type="checkbox"/> Scrap <input type="checkbox"/> Use-as-is <input type="checkbox"/> Work Order Update <input type="checkbox"/>	AGAINST DEPARTMENT/PROCESS <table style="width: 100%;"> <tr> <td>Skid-tube <input type="checkbox"/></td> <td>Crosstube <input type="checkbox"/></td> <td>Water Jet <input type="checkbox"/></td> <td>Engineering <input type="checkbox"/></td> </tr> <tr> <td>Machining <input type="checkbox"/></td> <td>Small Fab <input type="checkbox"/></td> <td>Prod. Eng. Coord. <input type="checkbox"/></td> <td>Quality <input type="checkbox"/></td> </tr> <tr> <td>Thermoforming <input type="checkbox"/></td> <td>Finishing <input type="checkbox"/></td> <td>Rec/Store/Packaging <input type="checkbox"/></td> <td>Other <input type="checkbox"/></td> </tr> <tr> <td>Large Fab <input type="checkbox"/></td> <td>Composite <input type="checkbox"/></td> <td>Supplier <input type="checkbox"/></td> <td></td> </tr> </table>	Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>	Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coord. <input type="checkbox"/>	Quality <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>	
Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>															
Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coord. <input type="checkbox"/>	Quality <input type="checkbox"/>															
Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>															
Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>																

Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector
Doc/Data <input type="checkbox"/>									
Equip/Tooling <input type="checkbox"/>									
Operator <input type="checkbox"/>									
Material <input type="checkbox"/>									
Setup <input type="checkbox"/>									
Other <input type="checkbox"/>									
Process <input type="checkbox"/>									
Supplier <input type="checkbox"/>									
Training <input type="checkbox"/>									
Unapproved <input type="checkbox"/>									

FAULT CATEGORY

Landing Gear <input type="checkbox"/> Bending <input type="checkbox"/> Centre Not Concentric to O/S <input type="checkbox"/> Cracks <input type="checkbox"/> Crushed/Crimped. <input type="checkbox"/> Cuffs <input type="checkbox"/> Heat Treat <input type="checkbox"/> Inspection Strip in Tube <input type="checkbox"/> Ripples in Bend <input type="checkbox"/> Torque Waves in Extrusion <input type="checkbox"/> Turning Sequence <input type="checkbox"/> Wave/Twist in Tube	General <input type="checkbox"/> Bend <input type="checkbox"/> BOM/Route <input type="checkbox"/> Broken/Damaged <input type="checkbox"/> Burrs <input type="checkbox"/> Contamination <input type="checkbox"/> Countersink <input type="checkbox"/> Cut Too Short <input type="checkbox"/> Drill Holes <input type="checkbox"/> Drawing <input type="checkbox"/> Finish <input type="checkbox"/> Folio	<input type="checkbox"/> Grain <input type="checkbox"/> Hardware <input type="checkbox"/> Inspection Incomplete <input type="checkbox"/> Instructions Incomplete/Unclear <input type="checkbox"/> Maintenance <input type="checkbox"/> Mislabeled <input type="checkbox"/> Misread <input type="checkbox"/> Offset <input type="checkbox"/> Out of Calibration <input type="checkbox"/> Out of Sequence <input type="checkbox"/> Outside Dimensions	<input type="checkbox"/> Ovalized <input type="checkbox"/> Over/Under tolerance <input type="checkbox"/> Part Incorrect <input type="checkbox"/> Part Lost/Missing <input type="checkbox"/> Part Moved <input type="checkbox"/> Positioned Wrong <input type="checkbox"/> Power Loss/Surge <input type="checkbox"/> Pressure/Forced <input type="checkbox"/> Temperature/Cure <input type="checkbox"/> Weld <input type="checkbox"/> Wrong Stock Pulled <input type="checkbox"/> Other
--	---	---	---

Picklist Print

February-14-13 10:51:03 AM

Page 1

Work Order ID: 97136

Parent Item: D3500-1

Parent Item Name: Saddle

Start Date: 2/14/13

Required Date: 3/08/13

Start Qty: 12.00

Required Qty: 12.00

Comments: IPP Rev:A New Issue 06-06-15 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D6102-013 Saddle Billet		Manufactured	No			100	Each	48.0000	1	12		SL 13-3-30	

Location	Loc Qty	Loc Code
MAT043	8	
60713	8	
MAT045	10	
90316	10	
MAT046	30	
95400	30	

95105

12

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: _____ Date: _____

QA Closed: _____ Date: _____

Work Order: _____ Part No. _____ NCR No. _____				DISPOSITION Rework <input type="checkbox"/> Scrap <input type="checkbox"/> Use-as-is <input type="checkbox"/> Work Order Update <input type="checkbox"/>		AGAINST DEPARTMENT/PROCESS <div style="display: flex; justify-content: space-between;"> <div> Skid-tube <input type="checkbox"/> Machining <input type="checkbox"/> Thermoforming <input type="checkbox"/> Large Fab <input type="checkbox"/> </div> <div> Crosstube <input type="checkbox"/> Small Fab <input type="checkbox"/> Finishing <input type="checkbox"/> Composite <input type="checkbox"/> </div> <div> Water Jet <input type="checkbox"/> Prod. Eng. Coord. <input type="checkbox"/> Rec/Store/Packaging <input type="checkbox"/> Supplier <input type="checkbox"/> </div> <div> Engineering <input type="checkbox"/> Quality <input type="checkbox"/> Other <input type="checkbox"/> </div> </div>					
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector		
Doc/Data <input type="checkbox"/>											
Equip/Tooling <input type="checkbox"/>											
Operator <input type="checkbox"/>											
Material <input type="checkbox"/>											
Setup <input type="checkbox"/>											
Other <input type="checkbox"/>											
Process <input type="checkbox"/>											
Supplier <input type="checkbox"/>											
Training <input type="checkbox"/>											
Unapproved <input type="checkbox"/>											

FAULT CATEGORY				
Landing Gear <input type="checkbox"/> Bending <input type="checkbox"/> Centre Not Concentric to O/S <input type="checkbox"/> Cracks <input type="checkbox"/> Crushed/Crimped <input type="checkbox"/> Cuffs <input type="checkbox"/> Heat Treat <input type="checkbox"/> Inspection Strip in Tube <input type="checkbox"/> Ripples in Bend <input type="checkbox"/> Torque Waves in Extrusion <input type="checkbox"/> Turning Sequence <input type="checkbox"/> Wave/Twist in Tube	General <input type="checkbox"/> Bend <input type="checkbox"/> BOM/Route <input type="checkbox"/> Broken/Damaged <input type="checkbox"/> Burrs <input type="checkbox"/> Contamination <input type="checkbox"/> Countersink <input type="checkbox"/> Cut Too Short <input type="checkbox"/> Drill Holes <input type="checkbox"/> Drawing <input type="checkbox"/> Finish <input type="checkbox"/> Folio	<input type="checkbox"/> Grain <input type="checkbox"/> Hardware <input type="checkbox"/> Inspection Incomplete <input type="checkbox"/> Instructions Incomplete/Unclear <input type="checkbox"/> Maintenance <input type="checkbox"/> Mislabeled <input type="checkbox"/> Misread <input type="checkbox"/> Offset <input type="checkbox"/> Out of Calibration <input type="checkbox"/> Out of Sequence <input type="checkbox"/> Outside Dimensions	<input type="checkbox"/> Ovalized <input type="checkbox"/> Over/Under tolerance <input type="checkbox"/> Part Incorrect <input type="checkbox"/> Part Lost/Missing <input type="checkbox"/> Part Moved <input type="checkbox"/> Positioned Wrong <input type="checkbox"/> Power Loss/Surge	<input type="checkbox"/> Pressure/Forced <input type="checkbox"/> Temperature/Cure <input type="checkbox"/> Weld <input type="checkbox"/> Wrong Stock Pulled <input type="checkbox"/> Other

DART AEROSPACE LTD		Work Order:	97136
Description: Saddle		Part Number:	D3500-1
Inspection Dwg: D3500		Rev: C	Page 1 of 1

				Recorded Actual Dimensions					
Dim	Min	Max	Go/No Go Gauge	1	2	3	4	By	Date
A	0.483	0.490		486	486	486	486		
B	1.175	1.185		1180	1180	1180	1180		
C	3.145	3.155		3.150	3.150	3.150	3.150		
D	1.175	1.185		1180	1180	1180	1180		
E	0.365	0.385		376	376	375	375		
F	0.490	0.510		498	498	499	499		
H									
(Note: Dimension I is 0.015" over flange)									
I	R1.575	R1.595		1.588	1.584	1.583	1.583		
J	0.240	0.260		241	249	250	251		
K	0.490	0.510		500	500	500	500		
L	3.590	3.650		3.620	3.620	3.620	3.620		
M	0.315	0.322		316	316	316	316		
N	0.256	0.262		259	259	259	259		
O	6.500	6.520		6.510	6.510	6.510	6.510		
P	5.990	6.010		5.986	6.002	6.000	6.000		
Q	2.820	2.830		2.825	2.825	2.825	2.825		
R	2.495	2.505		2.500	2.500	2.500	2.500		
S	2.245	2.255		2.250	2.250	2.250	2.250		
T	1.120	1.130		1.125	1.125	1.125	1.125		
U	0.540	0.560		546	552	550	550		
V	0.793	0.803		798	798	798	798		
W	R.240	R.260		250	250	250	250		
X	0.040	0.060		050	050	050	050		
Y	0.100	0.120		100	100	100	100		
AA	R1.125	R1.145		1.136	1.130	1.129	1.130		
AB	R.490	R.510		500	500	500	500		
AC	0.615	0.635		635	635	635	635		
AD	0.240	0.260		259	259	258	257		
AE	1.810	1.830		1.822	1.822	1.822	1.822		
AF	0.240	0.260		253	251	251	250		
AG	0.140	0.160		152	155	154	154		
AH	0.140	0.160		153	154	158	155		
AI	0.140	0.160		155	155	156	156		
Accept/Reject									

Measured by: SL	Audited by: FR
Date: 13-3-30	Date: 13/04/01

Rev	Date	Change	Revised by	Approved
A	06.09.26	New Issue	KJ/EC	
B	08.10.07	Dimension H removed	KJ/DD	
C	08.11.28	Dimension 'M' revised	KJ/EC	
D	11.01.17	Note added to Dim I	KJ	

DART AEROSPACE LTD		Work Order: 99136
Description: Saddle		Part Number: D3500-1
Inspection Dwg: D3500	Rev: C	Page 1 of 1

				Recorded Actual Dimensions					
Dim	Min	Max	Go/No Go Gauge	15	26	37	48	By	Date
A	0.483	0.490		486	486	486	486		
B	1.175	1.185		1.180	1.180	1.180	1.180		
C	3.145	3.155		3.150	3.150	3.150	3.150		
D	1.175	1.185		1.180	1.180	1.180	1.180		
E	0.365	0.385		375	375	375	375		
F	0.490	0.510		500	499	500	500		
H									
(Note: Dimension I is 0.015" over flange)									
I	R1.575	R1.595		1.583	1.583	1.582	1.583		
J	0.240	0.260		250	250	252	251		
K	0.490	0.510		500	500	500	500		
L	3.590	3.650		3.620	3.620	3.620	3.620		
M	0.315	0.322		316	316	316	316		
N	0.256	0.262		259	259	259	259		
O	6.500	6.520		6.519	6.510	6.510	6.510		
P	5.990	6.010		5.994	6.000	6.000	6.000		
Q	2.820	2.830		2.825	2.825	2.825	2.825		
R	2.495	2.505		2.500	2.500	2.500	2.500		
S	2.245	2.255		2.250	2.250	2.250	2.250		
T	1.120	1.130		1.125	1.125	1.125	1.125		
U	0.540	0.560		549	550	550	550		
V	0.793	0.803		798	798	798	798		
W	R.240	R.260		250	250	250	250		
X	0.040	0.060		050	050	050	050		
Y	0.100	0.120		100	100	100	100		
AA	R1.125	R1.145		1.129	1.129	1.129	1.130		
AB	R.490	R.510		500	500	500	500		
AC	0.615	0.635		635	635	635	635		
AD	0.240	0.260		258	258	259	257		
AE	1.810	1.830		1.822	1.822	1.820	1.821		
AF	0.240	0.260		250	250	250	249		
AG	0.140	0.160		153	153	152	153		
AH	0.140	0.160		154	156	157	155		
AI	0.140	0.160		156	156	157	156		
Accept/Reject									

Measured by: SL
Date: 13-3-30

Audited by: F.K.
Date: 13/04/01

Rev	Date	Change	Revised by	Approved
A	06.09.26	New Issue	KJ/EC	
B	08.10.07	Dimension H removed	KJ/DD	
C	08.11.28	Dimension 'M' revised	KJ/EC	
D	11.01.17	Note added to Dim I	KJ	



DART AEROSPACE LTD		Work Order: 97136
Description: Saddle		Part Number: D3500-1
Inspection Dwg: D3500	Rev: C	Page 1 of 1

				Recorded Actual Dimensions					
Dim	Min	Max	Go/No Go Gauge	19	20	21	22	By	Date
A	0.483	0.490		.486	.486	.486	.486		
B	1.175	1.185		1.180	1.180	1.180	1.180		
C	3.145	3.155		3.150	3.150	3.150	3.150		
D	1.175	1.185		1.180	1.180	1.180	1.180		
E	0.365	0.385		.375	.375	.375	.375		
F	0.490	0.510		.500	.500	.500	.500		
H									
(Note: Dimension I is 0.015" over flange)									
I	R1.575	R1.595		1.587	1.586	1.586	1.586		
J	0.240	0.260		.250	.249	.249	.250		
K	0.490	0.510		.500	.500	.500	.500		
L	3.590	3.650		3.620	3.620	3.620	3.620		
M	0.315	0.322		.316	.316	.316	.316		
N	0.256	0.262		.259	.259	.259	.259		
O	6.500	6.520		6.510	6.510	6.510	6.510		
P	5.990	6.010		6.001	6.000	6.000	6.000		
Q	2.820	2.830		2.825	2.825	2.825	2.825		
R	2.495	2.505		2.500	2.500	2.500	2.500		
S	2.245	2.255		2.250	2.250	2.250	2.250		
T	1.120	1.130		1.125	1.125	1.125	1.125		
U	0.540	0.560		.551	.550	.550	.550		
V	0.793	0.803		.798	.798	.798	.798		
W	R.240	R.260		.250	.250	.250	.250		
X	0.040	0.060		.050	.050	.050	.050		
Y	0.100	0.120		.100	.100	.100	.100		
AA	R1.125	R1.145		1.133	1.132	1.132	1.132		
AB	R.490	R.510		.500	.500	.500	.500		
AC	0.615	0.635		.635	.635	.635	.635		
AD	0.240	0.260		.253	.253	.253	.253		
AE	1.810	1.830		1.823	1.822	1.822	1.822		
AF	0.240	0.260		.250	.248	.248	.248		
AG	0.140	0.160		.155	.155	.155	.155		
AH	0.140	0.160		.154	.153	.153	.153		
AI	0.140	0.160		.155	.155	.155	.155		
Accept/Reject									

Measured by:	SL
Date:	13-3-30

Audited by:	F.K.
Date:	13/04/01

Rev	Date	Change	Revised by	Approved
A	06.09.26	New Issue	KJ/EC	
B	08.10.07	Dimension H removed	KJ/DD	
C	08.11.28	Dimension 'M' revised	KJ/EC	
D	11.01.17	Note added to Dim I	KJ	



D3500-1 SADDLE

- 1) MATERIAL: 6061-T6/T651 (QQ-A-200/8 OR QQ-A-250/11)
(MAKE FROM D6102-013 SADDLE BILLET, 6061)
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1,
POWDER COAT GLOSS WHITE (REF 4.3.5.1) PER
DART QSI 005 4.3
- 3) BREAK ALL SHARP EDGES 0.010 TO 0.020
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) ALL DIMENSIONS ARE IN INCHES

RELEASED

06-08-15

C	06.06.30	MAT'L NOW 6061-T6/T651
B	06.05.29	CHANGE DIMS; MAT'L NOW 7075-T7351
A	06.04.18	NEW ISSUE
DESIGN	PH	DART AEROSPACE LTD. WINDSOR, ONTARIO, CANADA
CHECKED	PH	DRAWING NO. D3500
DATE	06.06.30	TITLE SADDLE
REV. C		SHEET 1 OF 1
SCALE		2:3

COPYRIGHT © 2008 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL
AND IS SUPPLIED ON THE EXPRESS CONDITION
THAT IT IS NOT TO BE USED FOR ANY PURPOSE
OR COPIED OR COMMUNICATED TO ANY OTHER
PERSON WITHOUT WRITTEN PERMISSION FROM
DART AEROSPACE LTD.